



Office for Nuclear Regulation (ONR) Quarterly Site Report for Berkeley nuclear licensed site

Report for period 1 January – 31 March 2017

Foreword

This report is issued as part of ONR's commitment to make information about inspection and regulatory activities relating to the above site available to the public. Reports are distributed quarterly to members for the Berkeley Site Stakeholder Group and are also available on the ONR website (<http://www.onr.org.uk/llic/>).

A site inspector from ONR usually attends Berkeley Site Stakeholder Group meetings and will respond to any questions raised there. Any person wishing to inquire about matters covered by this report should contact ONR.

TABLE OF CONTENTS

1	INSPECTIONS	3
2	ROUTINE MATTERS	3
3	NON-ROUTINE MATTERS	4
4	REGULATORY ACTIVITY	4
5	NEWS FROM ONR	4
6	CONTACTS	5

1 INSPECTIONS

1.1 Dates of inspection

The ONR site inspector made inspections on the following dates during the quarter:

- 23 - 26 January 2017

2 ROUTINE MATTERS

2.1 Inspections

Inspections are undertaken as part of the process for monitoring compliance with:

- The conditions attached by ONR to the nuclear site licence granted under the Nuclear Installations Act 1965 (NIA65) (as amended);
- The Energy Act 2013;
- The Health and Safety at Work Act 1974 (HSWA74); and
- Regulations made under HSWA74, for example the Ionising Radiations Regulations 1999 (IRR99) and the Management of Health and Safety at Work Regulations 1999 (MHSWR99).

The inspections entail monitoring licensee's actions on the site in relation to incidents, operations, maintenance, projects, modifications, safety case changes and any other matters that may affect safety. The licensee is required to make and implement adequate arrangements under the conditions attached to the licence in order to ensure legal compliance. Inspections seek to judge both the adequacy of these arrangements and their implementation.

In this period, routine inspections of Berkeley covered the following:

- Compliance inspections in relation to:
 - Incidents on the site
 - Emergency arrangements
 - Management systems
 - Examination, inspection, maintenance and testing
 - Decommissioning (a joint inspection with the Environment Agency Regulator)
 - Organisational capability
- A meeting with the Safety Representatives.

In general, ONR judged the arrangements made and implemented by the site in response to safety requirements to be adequate in the areas inspected. However, where improvements were considered necessary, the licensee made satisfactory commitments to address the issues, and the site inspector will monitor progress during future visits. Where necessary, ONR will take formal regulatory enforcement action to ensure that appropriate remedial measures are implemented to reasonably practicable timescales.

2.2 Other work

Nothing to report.

3 NON-ROUTINE MATTERS

Licensees are required to have arrangements to respond to non-routine matters and events. ONR inspectors judge the adequacy of the licensee's response, including actions taken to implement any necessary improvements.

An ONR assessor discussed with the site the latest assessment of the future hazards and risks from the work with ionising radiation on the Berkeley site at the end of 2016. The results of his assessment will be made known to the Site shortly.

4 REGULATORY ACTIVITY

ONR may issue formal documents to ensure compliance with regulatory requirements. Under nuclear site licence conditions, ONR issues regulatory documents, which either permit an activity or require some form of action to be taken; these are usually collectively termed 'Licence Instruments' (LIs), but can take other forms. In addition, inspectors may issue Enforcement Notices to secure improvements to safety.

During the period no LIs were issued.

5 NEWS FROM ONR

New reactors update:

- ONR received a request from Government to begin the Generic Design Assessment process for the UK HPR1000 in January. The reactor is now in Step 1 of the GDA process.
- On 30 March, ONR issued Design Acceptance Confirmation for the AP1000@nuclear reactor, designed by Westinghouse. The regulators required 51 GDA issues to be resolved before confirming suitability of the design.
- ONR granted its first consent for the start of construction at Hinkley Point C licensed site. The consent covers the placement of the structural concrete for the first nuclear safety-related structure at the site.
- On 31 March, Horizon Nuclear Power submitted its application for a nuclear site licence to build and operate two UK Advanced Boiling Water Reactors at Wylfa Newydd on Anglesey.

Quarterly statement of civil incidents

ONR published its quarterly statement of civil incidents reporting on the period October-December 2016. There was one incident which met ministerial reportable criteria at Dounreay involving contamination of workers' clothing. There was no detectable intake of radioactive material by any of the people involved in the incident.

Regulation Matters magazine

Insight into ONR's work as an independent regulator of the nuclear industry can be found in Regulation Matters. This quarterly online publication (<http://www.onr.org.uk/regulation-matters.htm>) reports on the key themes and developments in each of ONR's regulatory programmes and provides an update about the on-going changes at ONR. For the latest news and updates from ONR, you can also visit the website and sign up for our e-bulletin: <http://www.onr.org.uk/index.htm>.

CONTACTS

Office for Nuclear Regulation
Redgrave Court
Merton Road
Bootle
Merseyside
L20 7HS

website: www.onr.org.uk

email: ONREnquiries@onr.gsi.gov.uk

This document is issued by the Office for Nuclear Regulation (ONR). For further information about ONR, or to report inconsistencies or inaccuracies in this publication please visit <http://www.onr.org.uk/feedback.htm>.

© Office for Nuclear Regulation, 2017

If you wish to reuse this information visit www.onr.org.uk/copyright.htm for details.

Published 04/17

For published documents, the electronic copy on the ONR website remains the most current publicly available version and copying or printing renders this document uncontrolled.