



Office for Nuclear Regulation (ONR) Site Report for Hunterston A

Report for period 1 October – 31 December 2021

Foreword

This report is issued as part of ONR's commitment to make information about inspection and regulatory activities relating to the above site available to the public. Reports are distributed to members for the Hunterston Site Stakeholder Group and are also available on the ONR website (<http://www.onr.org.uk/llc/>).

Site inspectors from ONR usually attend Hunterston Site Stakeholder Group meetings where they will respond to any questions raised there. Any person wishing to inquire about matters covered by this report should contact ONR.



Table of Contents

1 Inspections3

2 Routine Matters3

3 Non-Routine Matters.....4

4 Regulatory Activity5

5 News from ONR.....6

6 Contacts5

1 Inspections

Dates of inspection

The ONR site inspector made inspections at the Hunterston A (HNA) site on the following dates during the report period 1 October – 31 December 2021:

- 7 – 9 December 2021

2 Routine Matters

Inspections

Inspections are undertaken as part of the process for monitoring compliance with:

- the conditions attached by ONR to the nuclear site licence granted under the Nuclear Installations Act 1965 (NIA65) (as amended);
- the Energy Act 2013
- the Health and Safety at Work Act 1974 (HSWA74); and
- regulations made under HSWA74, for example the Ionising Radiations Regulations 2017 (IRR17) and the Management of Health and Safety at Work Regulations 1999 (MHSWR99).

The inspections entail monitoring licensee's actions on the site in relation to incidents, operations, maintenance, projects, modifications, safety case changes and any other matters that may affect safety. The licensee is required to make and implement adequate arrangements under the conditions attached to the licence in order to ensure legal compliance. Inspections seek to judge both the adequacy of these arrangements and their implementation.

In this period, ONR carried out the following planned inspections at HNA:

Licence Condition (LC) compliance inspections: - compliance inspections focus on single LC compliance sampled from areas across the site. Each area may include multiple systems. The LCs inspected during this period were: -

- LC7 Incidents
- LC26 Control & supervision of operations

During the reporting period, ONR judged the arrangements made and implemented by the site in response to safety requirements to be satisfactory in the areas inspected. Where improvements have been identified, the licensee has made a commitment to address those issues, and ONR inspectors will closely monitor progress during future site inspections. Where necessary, ONR will take formal regulatory enforcement action to ensure that appropriate remedial measures are implemented to reasonably practicable timescales. Members of the public, who would like further information on



ONR's inspection activities during the reporting period, can view site Intervention Reports at www.onr.org.uk/intervention-records on our website www.onr.org.uk. Should you have any queries regarding our inspection activities, please email contact@onr.gov.uk.

Other work

The site inspector held a periodic meeting with safety representatives, to support their function of representing employees and receiving information on matters affecting their health, safety and welfare at work.

3 Non-Routine Matters

Licensees are required to have arrangements to respond to non-routine matters and events. ONR inspectors judge the adequacy of the licensee's response, including actions taken to implement any necessary improvements.

There were no such matters or events of significance during the period.

COVID-19

In response to the Covid-19 pandemic all 12 of Magnox Ltd.'s (ML) licensed sites have put arrangements in place to ensure their workplaces are COVID-secure sites. The sites have returned to a new "normal" with many staff combining working from home and at site as appropriate, with project work restarted to ensure the safe and timely decommissioning of these sites. In this quarter, HNA has continued with a controlled return to service with a number of staff working from home and at site as appropriate and has progressed a significant way through their plans. The ML Internal Oversight team has checked independently that the pandemic and restart arrangements have been properly implemented.

Emergency preparedness is being maintained through a duty cover team at each site in accordance with ONR approved emergency arrangements. These arrangements include the provision to call in additional personnel and the emergency services onto site to assist ML staff. These plans have been regularly rehearsed and observed by ONR inspectors during emergency exercises in the past.

Overall ONR is content with the actions taken by ML to make safe the HNA site under these exceptional circumstances. The site inspector is in touch regularly with HNA personnel to discuss any changes to the arrangements and any potential emerging safety or regulatory issues.



4 Regulatory Activity

ONR may issue formal documents to ensure compliance with regulatory requirements. Under nuclear site licence conditions, ONR issues regulatory documents, which either permit an activity or require some form of action to be taken; these are usually collectively termed 'Licence Instruments' (LIs) but can take other forms. In addition, inspectors may take a range of enforcement actions, to include issuing an Enforcement Notice.

- No LIs, Enforcement Notices or Enforcement letters were issued during this period.

5 News from ONR

For the latest news and information from the Office for Nuclear Regulation, please read and subscribe to our regular email newsletter 'ONR News' at www.onr.org.uk/onrnews

6 Contacts

Office for Nuclear Regulation
Redgrave Court
Merton Road
Bootle
Merseyside
L20 7HS
website: www.onr.org.uk
email: Contact@onr.gov.uk

This document is issued by the Office for Nuclear Regulation (ONR). For further information about ONR, or to report inconsistencies or inaccuracies in this publication please visit <http://www.onr.org.uk/feedback.htm>.

© Office for Nuclear Regulation, 2022
If you wish to reuse this information visit www.onr.org.uk/copyright.htm for details.
Published 02/22

For published documents, the electronic copy on the ONR website remains the most current publicly available version and copying or printing renders this document uncontrolled.